




# BLASTING TIPS


## Gap Method - Blast Pattern Efficiency

The pattern you blast with can have a large effect on the amount of surface area you can blast in a specific time. The typical way most people blast creates an unnecessarily large area of overlap. By blasting and leaving a gap between passes equal to 1/2 the width of the blast pattern and blasting the gap the second time around, you force yourself to overlap the proper amount.



**MORE COVERAGE  
SAME TIME  
SAME WEAR & TEAR  
SAME MEDIA USAGE**

### Typical Overlap Method (Mostly Overlap - Less Coverage)



### 50% Gap Method (Less Overlap - More Coverage)

